


SEAKEEPER 2 GYRO BOLT-IN CLEARANCES

1. REMINDER! See Bolt-In
Installation drawing 90487.
WARNING! NEW, SEAKEEPER
SUPPLIED BOLTS MUST BE USED
FOR EACH INSTALLATION AND
REINSTALLATION. IT IS IMPERATIVE



THAT TORQUE AND THREADLOCKER GUIDELINES BE FOLLOWED.

2. Tight clearances from cable guide bands to hull structure. See below figure for dimensions and reference Seakeeper drawing 90487 for complete gyro envelope.

